



Material Safety Data Sheet

[OSHA 29 CFR 1910.1200]

The QUIKRETE® Companies
One Securities Centre
3490 Piedmont Road, Suite 1300
Atlanta, GA 30329

Emergency Telephone Number
(770) 216-9580

Information Telephone Number
(770) 216-9580

Revision: July 2003

MSDS AA

SECTION I: PRODUCT IDENTIFICATION

QUIKRETE® Product Name	Code #
QUIKWALL® LIQUID STUCCO	1320, 1321, 1322

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

Hazardous Components	CAS No.	PEL (OSHA) mg/M ³	TLV (ACGIH) mg/M ³
Limestone/Marble	1317-65-3	5	5
Acrylic Polymer	Not Hazardous	None	None
Clay	12174-11-7	15	10
Titanium Dioxide	13463-67-7	15	10
Ethylene Glycol	107-21-1	50 ppm (1)	50 ppm (1)

(1) Limits for Vapor & Mist

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

Solubility in Water: Dilutable.

Physical Appearance and Odor: White or tinted viscous liquid with a slight ether and ammonia odor. May contain granular white fillers.

Boiling Point: ~100 C (212 ° F)

Freezing Point: ~ -1 C (30 ° F)

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

Unusual Hazards: This water based dispersion can splatter at temperatures above 100 C (212 ° F). Polymer film can burn once the water has evaporated. Product also may contain less than 1 % of a solvent with a Flash Point of 120 C (248 ° F)

Extinguishing Agents: Use methods appropriate for surrounding fire.

Personal Protective Equipment: For fire fighting, wear self-contained breathing apparatus and full protective gear.

SECTION V - REACTIVITY DATA

Stability: This material is considered stable. However, avoid temperatures above 177C/350F, the onset of polymer decomposition. Thermal decomposition is dependent on time and temperature.

Hazardous Decomposition Products: Thermal decomposition may yield acrylic monomers.

Hazardous Polymerization: Will not occur.

Incompatibility: Avoid contact with strong oxidizing agents or strong alkalis.



Product: QUIKWALL® LIQUID STUCCO

MSDS AA

SECTION VI - HEALTH HAZARD DATA

Route(s) of Entry:	Inhalation?	Yes
	Skin?	Yes
	Ingestion?	Yes

HEALTH EFFECTS FROM OVEREXPOSURE

Inhalation of vapor or mist can cause the following: headache - nausea - irritation of nose, throat, and lungs

Eye Contact: Direct contact with material can cause irritation and possible corneal injury.

Skin Contact: Prolonged or repeated skin contact can cause slight irritation.

FIRST AID:

Skin: Thoroughly wash affected area with soap and water. Remove contaminated clothing.

Eye Contact: Flush with large amounts of water, lifting the upper and lower lids occasionally. Do not rub eyes. Product contains granular fillers which can scratch the cornea. Get medical attention.

Ingestion: If swallowed, give two glasses of water. If large amounts are ingested, induce vomiting with Ipecac syrup or by placing finger at the back of the throat. Never give anything by mouth to an unconscious person. Get medical attention.

Inhalation: Remove to fresh air if effects occur. Consult physician.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

AVOID SKIN AND EYE CONTACT AND AVOID BREATHING VAPORS.

Storage Conditions: Keep from freezing; material may coagulate. The minimum recommended storage temperature for this material is 1C/34F. The maximum recommended storage temperature for this material is 49C/120F.

Personal Protective Equipment:

Eye protection: Use chemical splash goggles (ANSI Z87.1 or approved equivalent)

Hand protection: Neoprene gloves are recommended. Gloves of other chemically resistant materials may not provide adequate protection.

SECTION VIII - CONTROL MEASURES

Spill and leak handling:

Keep spectators away. Floor may be slippery; use care to avoid falling. Contain spills immediately with inert materials (e.g. sand, earth). Transfer liquids and solid diking material to separate suitable containers for recovery or disposal.

CAUTION: Keep spills and cleaning runoff out of municipal sewers and open bodies of water.

Personal Protection

Ventilation:

Use local exhaust ventilation with a minimum capture velocity of 100 ft/min. (30 m/min.) at the point of vapor evolution. Refer to the current edition of Industrial Ventilation: A Manual of Recommended Practice published by the

Product: QUIKWALL® LIQUID STUCCO

MSDS AA

American Conference of Governmental Industrial Hygienists for information on the design, installation, use, and maintenance of exhaust systems.

Other Protective Equipment: Facilities storing or utilizing this material should be equipped with an eyewash facility.

WASTE DISPOSAL

Coagulate the emulsion by the stepwise addition of ferric chloride and lime. Remove the clear supernatant and flush to a chemical sewer. Incinerate liquid and contaminated solids in accordance with local, state, and federal regulations.

NOTE: The information and recommendations contained herein are based upon data believed to be correct. However, no guarantee or warranty of any kind, express or implied, is made with respect to the information contained herein.